




POLAR
=FASTENERS=



d	M 1,6	M 2	M 2,5	M 3	M 3,5	M 4
P (pitch)	0,35	0,4	0,45	0,5	0,6	0,7
dz (max)	0,8	1	1,2	1,4	1,7	2
l	2-8	2,5-10	3-12	3-16	4-20	4-20

d	M 5	M 6	M 8	M 10	M 12
P (pitch)	0,8	1	1,25	1,5	1,75
dz (max)	2,5	3	5	6	8
l	5-25	6-30	8-40	10-50	12-60