




**POLAR**  
=FASTENERS=



d	M 1,6	M 2	M 2,5	M 3	M 3,5	M 4	M 5	M 6	M 8	M 10
P (pitch)	0,35	0,4	0,45	0,5	0,6	0,7	0,8	1	1,25	1,5
dk	3	3,8	4,5	5,5	6	7	8,5	10	13	16
k	1,1	1,4	1,8	2	2,4	2,6	3,3	3,9	5	6
l	2-16	3-20	3-25	4-30	5-35	5-40	6-50	8-60	10-80	12-80