




POLAR
=FASTENERS=



d	M 1,2	M 1,6	M 2	M 2,5	M 3	M 3,5
P (pitch)	0,25	0,35	0,4	0,45	0,5	0,6
dt (max)	0,12	0,16	0,2	0,25	0,3	0,35
l	2-6	2-8	3-10	3-12	4-16	5-20

d	M 4	M 5	M 6	M 8	M 10	M 12
P (pitch)	0,7	0,8	1	1,25	1,5	1,75
dt (max)	0,4	0,5	1,5	2	2,5	3
l	6-20	8-25	8-30	10-40	12-50	14-60